

How To Order Part Number

M Series Assembly/ Panel-mount type



SERIES

SIZE

- 05 = M5
- 08 = M8
- 09 = M9
- 10 = M10
- 12 = M12
- 16 = M16
- 20 = M20
- 24 = RD24

TYPE

- FB = Female PCB type
- MB = Male PCB type
- FS = Female solder type
- MS = Male solder type
- FC = Female crimp type
- MC = Male crimp type
- FA = Female assembly
- MA = Male assembly
- FW = Female assy screw joint
- MW = Male assy screw joint
- MBS = Male PCB shield type
- FBS = Female PCB shield type
- FWS = Female shield assy screw joint
- MWS = Male shield assy screw joint

CODING

- A = A Coding
- B = B Coding
- C = C Coding
- D = D Coding
- S = S Coding
- X = X Coding
- T = T Coding

MOUNTING THREAD

- 0 = M12x1.0
- 1 = M15x1.0
- 2 = M16x1.5
- 3 = PG9
- 4 = PG7
- 5 = M20x1.5

INSERT DEGREE

- ST = Straight
- RA = Right angled

POLES

- 03 = 3 Poles
- 04 = 4 Poles
- 05 = 5 Poles
- 08 = 8 Poles
-
- 3+5 = 3+5 Poles
-

LOCKING SYSTEM

- F = Fixed screw
- I = Snap in
- P = Plastic fix screw
- Q = Quick-lock
- HD = Hex Die-cast screw

ASSEMBLY METHOD

- F = Front mount
- R = Rear mount
- FL = Flange